



TopSolid Shortcuts for Windows

No.	Action	Windows Shortcuts	Section
1	Comment Edition	F2	Operation Manager Shortcuts
2	Operation Search	F3	Operation Manager Shortcuts
3	Link edition	F4	Operation Manager Shortcuts
4	Show Layers Dialog Box	Ctrl + L	Operation Manager Shortcuts
5	Display Information On Selected Operation	Ctrl + I	Operation Manager Shortcuts
6	Display Database Structure On Selected Operation	Ctrl + D	Operation Manager Shortcuts
7	Cut Selected Operations	Ctrl + X	Operation Manager Shortcuts
8	Paste Selected Operation	Ctrl + V	Operation Manager Shortcuts
9	Stop or Start a Simulation	Spacebar	Simulation Shortcuts
10	Jump to The Next Move	/	Simulation Shortcuts
11	Jump to The Next New Z Point	Z	Simulation Shortcuts
12	Increase The Simulation Speed	+	Simulation Shortcuts
13	Reduce The Simulation Speed	-	Simulation Shortcuts
14	Left The Simulation	Esc	Simulation Shortcuts
15	Jump to The Simulation of The Next Operation	Tab	Simulation Shortcuts
16	Rotate The Selected Clamp In The Counter Clockwise Direction	+	Part Clamping Shortcuts
17	Rotate The Selected Clamp In The Clockwise Direction	-	Part Clamping Shortcuts
18	Open The Face Selection Where to Put The Clamp	F	Part Clamping Shortcuts
19	Lock/Unlock X Axis for Clamp Positioning	X	Part Clamping Shortcuts
20	Lock/Unlock Y Axis for Clamp Positioning	Y	Part Clamping Shortcuts
21	Lock/Unlock Z Axis for Clamp Positioning	Z	Part Clamping Shortcuts
22	On-Line Help	F1	Part Clamping Shortcuts
23	Information on Selected Element	F2	Part Clamping Shortcuts
24	Zoom	F3 & LMB	Part Clamping Shortcuts
25	Pan	F4 & LMB	Part Clamping Shortcuts
26	Axial Rotation Along X	F5 & LMB	Part Clamping Shortcuts
27	Axial Rotation Along Y	F6 & LMB	Part Clamping Shortcuts
28	Axial Rotation Along Z	F7 & LMB	Part Clamping Shortcuts
29	Graphical Section	F8 & LMB	Part Clamping Shortcuts
30	Spherical Rotation	F9 & LMB	Part Clamping Shortcuts
31	Reorganize The Floating Icon Bars	F11	Part Clamping Shortcuts
32	Display/Hide The Floating Icon Bars	F12	Part Clamping Shortcuts
33	Undo Step By Step	Ctrl + Z	Part Clamping Shortcuts
34	Exit of The Current Function	Esc	Part Clamping Shortcuts
35	Cancel All Actions of The Current Function	Ctrl + A	Part Clamping Shortcuts
36	Open/Close Symbolic Tree	Ctrl + O	Part Clamping Shortcuts
37	Fit Screen Zoom	Ctrl + 1	Part Clamping Shortcuts
38	Toggle Between Open TopSolid Documents	Ctrl + Tab	Part Clamping Shortcuts
39	Spherical Rotation	Ctrl + LMB	Part Clamping Shortcuts
40	Pan	Shift + LMB	Part Clamping Shortcuts
41	Zoom	Ctrl + Shift + LMB	Part Clamping Shortcuts
42	Go Back to The Initial State	Left Arrow key	Verification Shortcuts
43	Stop or Start a Verification	Spacebar	Verification Shortcuts
44	Next Cut	/	Verification Shortcuts
45	Show The Tool Path	T	Verification Shortcuts
46	Change The Tool Path Display	S	Verification Shortcuts
47	Display The Current WCS	A	Verification Shortcuts
48	Zoom on An Area of The Part	Z	Verification Shortcuts
49	Execute An Hardcopy	P	Verification Shortcuts
50	Increase The Verification Speed	+	Verification Shortcuts
51	Decrease The Verification Speed	-	Verification Shortcuts

learn more keyboard shortcuts at <https://tutorialtactic.com/>